

more sensors, more solutions



Presence PLUS® P4 GEO Setting Up a Basic Inspection

Purpose:

Creating a P4 GEO inspection requires the user to configure the inspection via interface software. The following steps guide the user through setup of a basic inspection.



Overview: Inspection Process using P4 Software

Before You Start:			
 Install Software 	Set Up	Tools	Run
 Confirm PC & Sensor are communicating 	Create Reference	Add Tools to an	Begin Inspection Process
 Fixture Sensor & Target 	iniaye	mspection	1100633

SET UP

The Setup Menu captures a reference image and sets the trigger options							
SCREEN	USER ACTION	NOTES					
PromotionThe set of the set of	 Click Start Click Next Select Create a new inspection Click OK System Save Help System Save Help Focus Trigger Trigger Options Focus Trigger State Orithuscus Office State State State Undo State State State State Undo State State	 In Auto Exposure, the sensor adjusts exposure and gain level for optimum contrast. If the Auto Exposure routine does not produce the desired results, manually adjust the exposure time and gain. If the image is not updating, click Continuous under trigger Options. Use the Focus number to optimize the image quality. The higher the number, the better. If the Focus number remains at zero, disable firewall software on the computer. Clicking Next exits the Setup screen to enter the tools screen. 					

More information online at bannerengineering.com/iknow

TOOLS The Tools Menu allows the user to build, view, and modify an inspection SCREEN **USER ACTION** NOTES **1** Click **Geometric Count** · Geometric Count will add a geometric count tool to the tool list in the Navigation/Results window. 2 Click Draw ROI • **Region of Interest** (ROI) indicates the feature the 3 Select Rectangle sensor will search in its Field of View (FOV). 4 Click, Hold, and Drag ROI • Enlarge or reduce the ROI by clicking the outer edge around the feature to be inspected. of the ROI. 5 Select Enable Remote Teach 6 Click Advanced tab Helr Geometric Count Tool Advanced 4 2 3 100 % 80 Enable Remote Tear tric Count Tool 6 TOOLS >> Advanced Tab SCREEN **USER ACTION** NOTES **7** Enter **Rotation Range** values • The default Rotation Range is +45, -45. For a full 360 degree rotation, +180, -180 should be used. 8 Click Apply • By clicking **Apply**, the edges (in blue) that constitute 9 Click Back the geometric pattern and the edges in the search (10) Click Next area are shown. • The sensor has now been told to find a pattern. • Clicking Next exits the Geometric Count Tool. Geometric Count Tool 7 inced Geometric Count Tool Advanced Ы

8

9

More information online at **bannerengineering.com/iknow**

10

Vision Sensor Software Training

TOOLS >> Test



USER ACTION





3 Select **GC_1**



NOTES

NOTES

- The Test Tool determines the pass/fail condition of the inspection and can drive an output.
- Clicking Next exits the Test Tool to enter the Tools screen.

2		Taal	+	Test Tes	1.00	4			44.0	"	:
ų	UICK	reach	sets the	e lest loc	i so	that It	WIII	pass	the	reference	Image

USER ACTION





• Quick Teach takes the current number of patterns found from GC_1 tool and imports those values (min = 1, max = 1) into the Test Tool automatically.

- The user can manually set the min/max values in the Test Tool GC_1 tab.
- The P4 GEO sensor has 12 inspection locations.

RUN



USER ACTION

- (1) Click **Start** at the bottom of the run window.
- 2 Select Next from Display section.
 - 3 Close Software Program in the Run Mode by clicking the **X** in the upper right corner.



NOTES

- After the inspection is saved to the sensor, the RUN screen is displayed.
- Trigger the sensor with an external trigger.
- 🗹 = Pass 🙋 = Fail
- The sensor continues to run after the software is closed.

Banner Engineering Corp.

9714 10th Avenue North • Minneapolis, Minnesota 55441 • (763) 544-3164 • Fax: (763) 544-3213 1-888-3-SENSOR (1-888-373-6767) • www.bannerengineering.com • e-mail: sensors@bannerengineering.com

more sensors, more solutions

P/N 120211 Rev. A