






VISION SENSOR SOFTWARE TRAINING




Increasing P4 GEO Count Tool Sensitivity



more sensors, more solutions

PresencePLUS® P4 GEO

Increasing GEO Count Tool Sensitivity



Purpose:

The GEO Count Tool is an inspection tool that finds patterns in an image. The following steps explain how to increase GEO Count Tool sensitivity in an inspection scenario to better distinguish between good and bad patterns.

Overview: Inspection Process using P4 Software

Before You Start:

- Install Software
- Confirm PC & Sensor are communicating
- Fixture Sensor & Target
- Setup a P4 GEO Basic Inspection*



Application Example

Example of a GEO Count Tool using the minimum acceptable sensitivity to verify a part number


- Three different part numbers all pass.
- The default Minimum Acceptance Level does not provide enough sensitivity.
- Use the "Extra Edges" and "Missing Edges" features to increase the GEO Count Tool's sensitivity.



Incorrect part number "062204"



Correct part number "062104"




Missing character "06210_"

TOOLS >> GEO COUNT


Check for Missing Edges

SCREEN	USER ACTION	NOTES
	<ol style="list-style-type: none"> 1 Click GC_1 2 Click Advanced tab 3 Select Check For Missing Edges 4 Click Apply 	<ul style="list-style-type: none"> • "Check for Missing Edges" configures the P4 GEO to "fail" the pattern if one edge segment of at least 5 pixels (default) or more is missing. In the failed example below, the edges from the "4" are missing. • If the tool is too sensitive (rejects "good" parts), increase the "Minimum Edge Length", located on the Advanced tab above the 5 pixel default. • If the tool is not sensitive enough (passes "bad" parts), decrease the "Minimum Edge Length", located on the Advanced tab below the 5 pixel default.


GO TO RUN MODE AND VIEW FOLLOWING EXAMPLES:



✓ Correct part number "062104" passes



✓ Incorrect part number "062204" passes



✗ Missing character "06210_" fails

TOOLS >> GEO COUNT


Check for Extra Edges

SCREEN	USER ACTION	NOTES
	<ol style="list-style-type: none"> 1 Return to the Tool Screen (not shown) 2 Click GC_1 3 Click Advanced tab 4 Unselect Check For Missing Edges 5 Select Check For Extra Edges 6 Click Apply 	<ul style="list-style-type: none"> • "Check for Extra Edges" configures the P4 GEO to "fail" the pattern if an edge is found that is 5 pixels (default) or more in a location that did not have an edge before. In the failed example, below the "2" has more edge content than the "1" so the inspection fails. • If the tool is too sensitive (rejects "good" parts) increase the "Minimum Edge Length", located on the Advanced tab above the 5 pixel default. • If the tool is not sensitive enough (passes "bad" parts) decrease the "Minimum Edge Length", located on the Advanced tab below the 5 pixel default.


GO TO RUN MODE AND VIEW FOLLOWING EXAMPLES:



✓ Correct part number "062104" passes



✗ Incorrect part number "062204" fails



✓ Missing character "06210_" passes


*See "Setting Up a P4 GEO Basic Inspection Setup Guide" P/N 120211.

TOOLS >> GEO COUNT

Check for Missing and Extra Edges

SCREEN	USER ACTION	NOTES
	<ol style="list-style-type: none"> 1 Return to the Tool Screen (not shown) 2 Click GC_1 3 Click Advanced tab 4 Select Check For Extra Edges 5 Select Check For Missing Edges 6 Click Apply 	<ul style="list-style-type: none"> • It is generally a good practice to check both Missing and Extra Edges in a single GEO Count Tool. • If the tool is too sensitive (rejects "good" parts) increase the "Minimum Edge Length", located on the Advanced tab above the 5 pixel default. • If the tool is not sensitive enough (passes "bad" parts) decrease the "Minimum Edge Length", located on the Advanced tab below the 5 pixel default.


GO TO RUN MODE AND VIEW FOLLOWING EXAMPLES:



✓ Correct part number "062104" passes



✗ Incorrect part number "062204" fails



✗ Missing character "06210_" fails

*See "Setting Up a P4 GEO Basic Inspection Setup Guide" P/N 120211.